SOCIA COUCHEZ RELIEF DRAIN - Near Shore Site n14

Z scores of indicator measurements at site n14 relative to all near shore sites
(Actual values for each indicator are given above each bar)
See Site Summary Date Key for color key, value units, abbreviations, and critical values.